

Technical Bulletin

2201 Dwyer Ave. • P.O. Box 4729 • Utica, NY 13504-4729 • Ph: 315-797-1310 • Fax: 315-797-3762 • E-Mail: info@ecrinternational.com • Web: www.ecrinternational.com

BULLETIN NO. 5282013-UB



DATE: May 28, 2013

PRODUCT: Utica Boiler UB90-100 II / III

FROM: Technical Service Department

TITLE: Direct Spark Ignition (DSI) to Hot Surface Ignition (HSI) Upgrade

MODELS AFFECTED:

UB90-50 Series II	UB90-75 Series II	UB90-100 Series II / III
-------------------	-------------------	--------------------------

SERIAL NO. RANGE: First four digits: **3412 – 5212** (34th - 52nd week / 2012)

0113 – 0313 (1st - 3rd week / 2013)

SITUATION: Utica Boilers upgrade from Direct Spark Ignition (DSI) to Hot Surface Ignition (HSI) on all Series II and Series III boilers manufactured from August 20, 2012 – January 18, 2013.

SOLUTION: The below kits are available thru the distributor normal purchase order channels for field upgrade to the aforementioned model boilers. These kits will be available to qualified installers to upgrade these specific boilers from DSI to a HSI ignition system.

Kit	Model	Fuel	Updates Series Listed
Number	Description	Туре	Below to Series IV
550002825	UB 90-50	Nat/LP	Series II
550002826	UB 90-75	Nat only	Series II
550002828	UB 90-75	LP only	Series II
550002827	UB 90-100	Nat / LP	Series III
550002829	UB 90-100	Nat only	Series II