

# **Technical Bulletin**

**BULLETIN NO. 112105** 

DATE: November 21, 2005

TO: All Utica Boiler Customers

**FROM:** Technical Service Department

**TITLE:** Burner Tube Change

## **MODELS AFFECTED**

MGB 50 thru 300 Nat and LP gas	Spark and std. pilot
--------------------------------	----------------------

## **SITUATION**

The current burner tubes used on the MGB-series Utica Boilers have been obsoleted and replaced with a new style burner of advanced design (see photo 1). The new burners were designed for quiet operation and better performance under harsh field conditions, i.e. L.P. Gas.

### MGB300:

The MGB300 requires a slight change to the burner door to accommodate the new tubes. Kit no. **550001347** is to be used in the event the new tubes are used to replace old style tubes in the field. This kit includes a new burner door along with the new burner tubes (see photo 2).

#### MGB 50 thru 250

The new style tubes, part no. **240005543** are a direct replacement for the old style tubes on the MGB50 thru 250 and require no burner door change.

## **EFFECTIVE DATE:**

As of November 14, 2005, all MGB series boilers began being built with the new style burner tubes.

**OVER** 




Photo 1




Photo 2

If you should have any questions, please feel free to contact our **Technical Service Department** at **1-800-325-5479**.